



November 14, 2017

Description	Church	School	Rectory	Parish	Wishes
Groups					
1	H.C. Accessibility	Safety	H.C. Accessibility	Great School / Community / History	Parish Center
	Safety		Safety		Meeting Rooms
	Grade Issues-Standing Water		Need Better Office Space	Priest / History	Connect Church & School
	Covered Canopy				More Room for CCD
	Cry Room - Space for Children				Multi-Purpose Room
	Accessible Sanctuary				Bride's Room
	H.C. Parking				Room for Children
	Cushions on Pews				MoreStorage - Lockable
	No First Floor Restrooms				First Floor Restrooms
2	Needs New Paint Job		Not H.C. Accessible	Presence of Holy Spirit Here	Padded Pews
	H.C. Restrooms		Impediment to M.P.	Historical Lineage Here	Build It and They Will Come
	Hearing Loop		No Accessible/Garages	Lack of Kids & Young Families	Ability to Pay for Projects
	H.C. Parking Spaces				H.C. Restrooms
	Heating/Air Conditioning				Improvement of Railings
	Communion Rail				Remove Stairs
	Carpeting/New Floor				Attract New People with M.P.
	Grade Issues-Standing Water				Get Younger
	Poor Lighting				Make this 'Home'
					Area for Wakes
3	Elevator Too Small for Casket		No Value in Renovating	Polish Heritage	Youth Center
	Dimmer Control for Lighting		Garage Space is Too Small	Pope John Paul II Visit Here	First Floor Restroom
	Wake Room - Like St. Peter's				Hearing Loop
	No H.C. Restrooms				Better Sound System
	Poor Sound System				Drive-Thru Canopy
	Grade Issues-Standing Water				New Rectory in Lieu of Alteration
	Elevator Back-Up / Delays				Design to Attract Weddings
	More Storage Needed				Add Garages to Rectory
	Railings Are Horrible				
	Kitchen Space is Too Tight				



November 14, 2017

Description	Church	School	Rectory	Parish	Wishes
4 Cemetery	Elevator Too Small for Casket	No Space for Office	Move Offices Out of Rectory	Historical Lineage Here	Drive-Thru Canopy
	No Covered Canopy	No Space for IT	Not Enough Storage Space		Create 1 Main Entrance (Security)
	Area Too Small for Wake	Music Room Not Connected			Need H.C. Restrooms
	Area Too Small for Coffee/Donuts	No Principal's Office			Adoration Chapel
	Too Many Entrances (Security)	Not Enough Storage Space			
	No H.C. Restrooms				
	No Restrooms Close to Entrances				
	Lack of Storage				
5 School		Single Pane Windows			Replace Windows
		No H.C. Restrooms			H.C. Restrooms
		Need Better Security			New Secure Entry System
		Need New Flooring			New Flooring
		Need Better Lighting			New Lighting
		Need More Classroom Storage			Additional Classroom Storage
		Need Bus Loading Signage			Loading Zone Signage
		No Workroom			New Workroom
		No Meeting Room			New Meeting Room
		Need School Office			Combined Parish/School Office
		Need Principal Office			New Principal Office
		No Air Conditioning			Air Conditioning
		No Multi-Purpose Space			Multi-Purpose Space
		Music Room is Separated			New Music Room
		Library Needs Updating			
		No Wireless Access in Building			
	Playground Design - Security				
	No Playground Fencing				
6	Replace Flooring		Offices Should Be W/School	History & Lineage	New Flooring
	No H.C. Restrooms			Feeling of Community	New H.C. Restrooms
					Combined School/Church Offices



November 14, 2017

Description	Church	School	Rectory	Parish	Wishes
7	Need New Paint				New Painting
	Poor Flooring				New Flooring
	Poor HVAC				Improve HVAC
	No Air Conditioning				Air Conditioning
	Lack of Storage				Add Storage
8 CCD-Choir	Poor Lighting	No Multi-Use Space			Improve Lighting
	20-30 Seats for Choir Needed				Improve Choir Seating
	No Communion Rail				Provide Communion Rail
	Flooring-Poor Acoustics				Fix Church Acoustics
	Lack of Outlets In Choir Balcony				Add Outlets in Choir
	No Room for Printer				Reorganize Choir Storage Room
	Poor Storage for Music Library				Add Music Library Stor. Furniture
	No 'Real' Area for Wakes				New Wake Area
	CCD needs two more classrooms				Add Two Rooms for CCD
	No CCD Office				Add CCD Office
	No Restrooms @ Church Entries				Add Restrooms @ Church Entries
	No Covered Entrance				Add Covered Entrance
9 Rosary	No Place for Crying Children				Add Room for Children
	Interior Church Needs Painting				Paint Church
	Pews in Poor Shape				Refinish Pews-Add Cushions
	Flooring in Poor Shape				New Flooring
	Poor Sound System				New Sound System
	Poor Heating				Improve Heat
	No H.C. Restrooms				H.C. Restrooms
	No Communion Rail				Add Communion Rail
	Lack of Storage				Add Storage
	Confessional not H.C. Accessible				H.C. Accessible Confessional
	No Air Conditioning				Air Conditioning
	No Space for Wakes				Space for Wakes



November 14, 2017

Description	Church	School	Rectory	Parish	Wishes
10 Fr. Greg	Poor Vehicular Circulation	Not Planned for the Future	Offices Should Be With School	History & Lineage	Need School Office Space
	Poor Pedestrian Circulation		H.C. Accessibility Throughout	Epicenter of U.S. Polish Migration	Need Masterplan
	No Campus Masterplan		More Garage Space	Divine Mercy	Combined Offices
	Storage Space			People / Community	Storage Space
				Bones of Existing Church	School Staff Rm, H.C. Toilets
				Traditions	School Multi-Purpose Room
				Pope John Paul II	Rectory Garage Space
				Brother Miller' - Possible Saint	Image That Reinforces Heritage
					Casket Friendly Elevator
					Communion Rail
				Adoration Chapel - Nice to Have	

11 History	1865 - Church 1 Built	x	x	Fires Played Huge Role in History	x
	1872 - Church 1 - Moved			Polish Center in Wisconsin	x
	1875 - Convent 1/ School Built			The Name 'Polonia'	x
	1875-Convent 1 / School Fire			Seating for 700+ People	x
	1875 - Convent 2/ School Built			x	x
	1875-Convent 2/ School Fire			x	x
	1876 - Convent 3/ School Built			x	x
	1876 - 'Sacred Heart' Church 2 Built			x	x
	1902 - 'Sacred Heart' Church 3 Built				x
	1934 - 'Sacred Heart' Church 3 Fire				x
	1934 - 'Sacred Heart' Church 4 Built				x